

# CHEVRON'S FRAUDULENT REMEDIATION

---

## Results from Expert Report in *Aguinda v. ChevronTexaco*

Evidence at trial demonstrates that laboratory sampling results in 45 out of 54 Chevron "remediated" pits have illegal levels of Total Petroleum Hydrocarbons. Chevron certified to the Ecuadorian government that it had "completely remediated" these pits. Evidence such as this forms the basis of a criminal fraud indictment against two Chevron lawyers.

#	SITE	CHEVRON'S CLAIM	TPH	NUMBER OF TIMES OVER LEGAL LIMIT
1	Sacha 18	Complete Remediation	35,380	35.3
2	Sacha 65	Complete Remediation	32,444	32.4
3	Shushufindi 27	Complete Remediation	26,413	26.4
4	Atacapi 5	Complete Remediation	21,976	21.9
5	Sacha 21	Complete Remediation	17,000	17.0
6	Shushufindi 21	Complete Remediation	16,033	16.0
7	Shushufindi 67	Complete Remediation	13,587	13.5
8	Shushufindi 45A	Complete Remediation	13,290	13.2
9	Shushufindi 48	Complete Remediation	13,000	13.0
10	Shushufindi 7	Complete Remediation	12,715	12.7
11	Shushufindi 25	Complete Remediation	10,956	10.9
12	Shushufindi 27	Complete Remediation	10,452	10.4
13	Ron 1	Complete Remediation	9,632	9.6
14	Lago Agrio 5	Complete Remediation	8,830	8.8
15	Sacha 94	Complete Remediation	8,700	8.7
16	Aguarico 8	Complete Remediation	8,183	8.1
17	Sacha 57	Complete Remediation	8,100	8.1
18	Sacha 65	Complete Remediation	7,519	7.5
19	Sacha 53	Complete Remediation	7,430	7.4
20	Shushufindi 13	Complete Remediation	7,415	7.4
21	Sacha 51	Complete Remediation	7,200	7.2
22	Shushufindi 45A	Complete Remediation	5,721	5.7

# CHEVRON'S FRAUDULENT REMEDIATION

---

23	Sacha 94	Complete Remediation	5,600	5.6
24	Shushufindi 25	Complete Remediation	5,574	5.5
25	Guanta 4	Complete Remediation	5,510	5.5
26	Shushufindi 7	Complete Remediation	5,334	5.3
27	Shushufindi 48	Complete Remediation	5,000	5.0
28	Shushufindi 18	Complete Remediation	4,881	4.8
29	Lago Agrio 2	Complete Remediation	4,777	4.7
30	Auca 19	Complete Remediation	4,014	4.0
31	Yuca 28	Complete Remediation	3,876	3.8
32	Shushufindi 46	Complete Remediation	3,697	3.6
33	Sacha 56	Complete Remediation	3,600	3.6
34	Sacha 6	Complete Remediation	3,300	3.3
35	Shushufindi 21	Complete Remediation	3,133	3.1
36	Sacha 51	Complete Remediation	3,100	3.1
37	Shushufindi 48	Complete Remediation	3,000	3.0
38	Sacha 10	Complete Remediation	2,802	2.8
39	Shushufindi 48	Complete Remediation	2,700	2.7
40	Sacha 57	Complete Remediation	2,400	2.4
41	Shushufindi 24	Complete Remediation	2,180	2.1
42	Parahuacu 3	Complete Remediation	2,065.1 2	2.065
43	Shushufindi 24	Complete Remediation	2,000	2.0
44	Shushufindi 8	Complete Remediation	1,600	1.6
45	Lago Agrio 6	Complete Remediation	1,300	1.3

Contact: Karen Hinton, 703-798-3109

[Karen@hintoncommunications.com](mailto:Karen@hintoncommunications.com)

Chart adapted by Amazon Defense Coalition

September 2008