

# CHEVRON'S ECUADOR TRIAL

## SHAM "REMEDIAATION" OF CONTAMINATED SITES

100% of the inspected sites that were supposedly cleaned-up by Chevron show high levels of toxins that violate the law

Inspected Site	Samples Taken by Chevron	Samples Taken by Affected Communities	Total Samples	Samples that Violate Ecuadorian Law*	Percentage that Violate Ecuadorian Law
SA-6	45	-	45	24	53%
SA-21	36	-	36	23	64%
SA-10	10	2	12	6	50%
SA-65	18	12	30	16	53%
SA-51	32	7	39	21	54%
SA-57	37	-	37	18	49%
SA-53	34	12	46	20	43%
SA-94	27	7	34	18	53%
SSF-67	30	14	44	33	82%
SSF-48	41	16	57	41	72%
SA-18	37	13	50	35	70%
SSF-08	22	12	34	22	65%
SSF-07	19	10	29	27	93%
SSF-21	17	11	28	21	75%
SSF-13	15	11	26	19	73%
SSF-18	25	12	37	25	67%
SSF-24	21	14	35	22	63%
SSF-27	23	7	30	27	90%
LAGO-02	25	9	34	18	53%
SACHA CENTRAL	29	9	38	29	76%
SSF-NORTE	48	-	48	31	65%
SSF-SUR	51	18	69	34	49%
SSF-SW	14	13	27	17	63%
SACHA NORTE 2	64	9	73	40	55%
AGUARICO	30	17	47	37	79%
SSF-04	8	8	16	14	87%
SSF-38	19	12	31	26	84%
SSF- 45 <sup>a</sup>	26	14	40	35	87%
LAGO-06	28	8	36	34	94%
SA-13	31	16	47	39	83%
SA-85	21	9	30	22	73%
SA-14	30	18	48	35	73%
SSF-CENTRAL	3	10	13	7	54%
LAGO NORTE	35	28	63	50	79%
<b>TOTAL</b>	<b>1123</b>	<b>418</b>	<b>1541</b>	<b>1053</b>	<b>68%</b>

Of sites (in green) supposedly cleaned-up by Chevron, 100% contain high toxic levels

\* Decrees 1215 and 3516, which regulate environmental law in Ecuador.

### CONCLUSIONS:

- (1) OF ALL THE SAMPLES REPORTED TO THE COURT BY BOTH SIDES, 1053 OF 1541 TAKEN (68%) VIOLATE ECUADORIAN LAW.
- (2) 100% OF THE INSPECTED SITES HAD LEVELS OF TOXINS THAT VIOLATE ECUADORIAN LAW.