

# Chevron's Ecuador Trial

## WATER SAMPLES FROM CONTAMINATED SITES/TEXACO

Of 135 water samples analyzed by Texaco in 22 inspected sites, 132 (98%) violate Ecuadorian law.

Inspection Sites	Water samples analyzed by Texaco	Number that violate Ecuadorian law*	% violating Ecuadorian law
SA-6	14	14	100%
SA-21	6	6	100%
SA-10	1	1	100%
SA-65	1	1	100%
SA-51	2	2	100%
SA-57	5	5	100%
SA-53	1	1	100%
SA-94	3	3	100%
SSF-67	8	8	100%
SSF-48	1	1	100%
SA-18	9	8	89%
SA-85	4	3	75%
SA-14	8	8	100%
SSF-08	6	6	100%
SSF-04	2	2	100%
SSF-07	10	10	100%
SSF-21	3	2	67%
SACHA CENTRAL	16	16	100%
LAGO NORTE	4	4	100%
SSF-SUR	12	12	100%
SSF-SW	10	10	100%
SSF-NORTE	9	9	100%
<b>TOTAL</b>	<b>135</b>	<b>132</b>	<b>98%</b>

\*Decreces 1215 and 3516, which regulate environmental contamination in Ecuador.

# Chevron's Ecuador Trial

## WATER SAMPLES FROM CONTAMINATED SITES/PLAINTIFFS

All 53 water samples analyzed by the plaintiffs from 22 inspected sites violate Ecuadorian law.

Inspection site	Water samples analyzed by the plaintiffs	Number violating Ecuadorian law	% violating Ecuadorian law
SA-6	-	-	
SA-21	-	-	
SA-10	1	1	100%
SA-65	2	2	100%
SA-51	1	1	100%
SA-57	-	-	-
SA-53	2	2	100%
SA-94	2	2	100%
SSF-67	4	4	100%
SSF-48	1	1	100%
SA-18	4	4	100%
SA-85	3	3	100%
SA-14	6	6	100%
SSF-08	4	4	100%
SSF-04	1	1	100%
SSF-07	-	-	-
SSF-21	1	1	100%
SACHA CENTRAL	4	4	100%
LAGO NORTE	8	8	100%
SSF-SUR	6	6	100%
SSF-SW	3	3	100%
SSF-NORTE	-	-	-
<b>TOTAL</b>	<b>53</b>	<b>53</b>	<b>100%</b>

\*Decrees 1215 and 3516, which regulate environmental contamination in Ecuador.

# Chevron's Ecuador Trial

## WATER SAMPLES FROM CONTAMINATED SITES

Of 188 water samples analyzed by both parties from 22 inspected sites, 185 (98%) violate Ecuadorian law.

Inspection site	Water samples analyzed by Texaco	Number that violate Ecuadorian law*	% violating Ecuadorian law	Water samples analyzed by plaintiffs	Number violating national law	% violating Ecuadorian law
SA-6	14	14	100%	-	-	
SA-21	6	6	100%	-	-	
SA-10	1	1	100%	1	1	100%
SA-65	1	1	100%	2	2	100%
SA-51	2	2	100%	1	1	100%
SA-57	5	5	100%	-	-	-
SA-53	1	1	100%	2	2	100%
SA-94	3	3	100%	2	2	100%
SSF-67	8	8	100%	4	4	100%
SSF-48	1	1	100%	1	1	100%
SA-18	9	8	89%	4	4	100%
SA-85	4	3	75%	3	3	100%
SA-14	8	8	100%	6	6	100%
SSF-08	4	4	100%	4	4	100%
SSF-04	2	2	100%	1	1	100%
SSF-07	10	10	100%	-	-	-
SSF-21	3	2	67%	1	1	100%
SACHA CENTRAL	16	16	100%	4	4	100%
SSF-NORTE	9	9	100%	-	-	-
LAGO NORTE	6	6	100%	8	8	100%
SSF-SUR	12	12	100%	6	6	100%
SSF-SW	10	10	100%	3	3	100%
<b>TOTAL</b>	<b>135</b>	<b>132</b>	<b>98%</b>	<b>53</b>	<b>53</b>	<b>100%</b>

\*Decreces 1215 and 3516, which regulate environmental contamination in Ecuador.

**Conclusions:** (1) Of the 188 water samples presented by the two parties to the court, 185 (98%) violate Ecuadorian law.  
 (2) Each of the inspected sites (100%) present water samples with toxin levels that violate Ecuadorian law.

December 2005/Amazon Defense Coalition