

# Chevron's Ecuador Trial

## SOIL SAMPLES IN CONTAMINATED SITES/TEXACO

Of 512 soil samples analyzed by Texaco from 22 inspected sites, 240 (47%) violate Ecuadorian law.

Inspection site	Soil samples analyzed by Texaco	Number that violate Ecuadorian law*	% violating Ecuadorian law
SACHA 6	31	10	32%
SACHA 21	30	17	57%
SACHA 10	9	3	33%
SACHA 65	17	7	41%
SACHA 51	30	12	40%
SACHA 57	32	13	40%
SACHA 53	33	7	21%
SACHA 94	24	8	33%
SACHA 18	28	14	50%
SACHA 85	17	10	59%
SSF-67	22	11	50%
SSF-48	40	24	60%
SACHA-14	22	12	55%
SSF-08	18	6	33%
SSF-04	6	4	67%
SSF-07	9	9	100%
SSF-21	14	13	93%
SACHA CENTRAL	13	4	31%
LAGO NORTE	35	22	63%
SSF-NORTE	39	22	56%
SSF-SUR	39	9	23%
SSF-SW	4	3	75%
<b>TOTAL</b>	<b>512</b>	<b>240</b>	<b>47%</b>

\*Decrees 1215 and 3516, which regulate environmental contamination in Ecuador.

# Chevron's Ecuador Trial

## SOIL SAMPLES IN CONTAMINATED SITES/PLAINTIFFS

Of 166 soil samples analyzed by the plaintiffs from 22 inspected sites, 132 (79%) violate Ecuadorian law.

Inspection site	Soil samples analyzed by the plaintiffs	Number that violate Ecuadorian law	% violating Ecuadorian law
SACHA 6	-	-	-
SACHA 21	-	-	-
SACHA 10	1	1	100%
SACHA 65	10	6	60%
SACHA 51	6	6	100%
SACHA 57	-	-	-
SACHA 53	10	10	100%
SACHA 94	5	5	100%
SACHA 18	9	9	100%
SACHA 85	6	6	100%
SSF-67	10	10	100%
SSF-48	15	15	100%
SACHA-14	12	9	75%
SSF-08	8	6	75%
SSF-04	7	7	100%
SSF-07	10	8	80%
SSF-21	10	5	50%
SACHA CENTRAL	5	5	100%
LAGO NORTE	20	16	80%
SSF-NORTE	-	-	-
SSF-SUR	12	7	58%
SSF-SW	10	1	10%
<b>TOTAL</b>	<b>166</b>	<b>132</b>	<b>79%</b>

\*Decrees 1215 and 3516, which regulate environmental contamination in Ecuador.

# Chevron's Ecuador Trial

## SOIL SAMPLES IN CONTAMINATED SITES

Of 678 soil samples analyzed by the two parties from 22 inspected sites, 372 (55%) violate Ecuadorian law.

Inspection site	Soil samples analyzed by Texaco	Number violating Ecuadorian law*	% violating Ecuadorian law	Soil samples analyzed by the plaintiffs	Number violating Ecuadorian law	% violating Ecuadorian law
SACHA 6	31	10	32%	-	-	
SACHA 21	30	17	57%	-	-	
SACHA 10	9	3	33%	1	1	100%
SACHA 65	17	7	41%	10	6	60%
SACHA 51	30	12	40%	6	6	100%
SACHA 57	32	13	40%	-	-	-
SACHA 53	33	7	21%	10	10	100%
SACHA 94	24	8	33%	5	5	100%
SACHA 18	28	14	50%	9	9	100%
SACHA 85	17	10	59%	6	6	100%
SSF-67	22	11	50%	10	10	100%
SSF-48	40	24	60%	15	15	100%
SACHA 14	22	12	55%	12	9	75%
SSF-08	18	6	33%	8	6	75%
SSF-04	6	4	67%	7	7	100%
SSF-07	9	9	100%	10	8	80%
SSF-21	14	13	93%	10	5	50%
SACHA CENTRAL	13	4	31%	5	5	100%
SSF- NORTE	39	22	56%	-	-	-
LAGO NORTE	35	22	63%	20	16	80%
SSF-SUR	39	9	23%	12	7	58%
SSF-SW	4	3	75%	10	1	10%
<b>TOTAL</b>	<b>512</b>	<b>240</b>	<b>47%</b>	<b>166</b>	<b>132</b>	<b>79%</b>

\*Decreces 1215 and 3516, which regulate environmental contamination in Ecuador.

**Conclusions:** (1) Of all the soil samples reported by both parties to the court, 372 of the 678 (55%) violate Ecuadorian law.  
 (2) Of the inspected sites, 100% present soil samples with levels of toxins that violate Ecuadorian law.