

# Chevron's Ecuador Trial

## SUMMARY OF SCIENTIFIC RESULTS

**100% of Sites Inspected by the Court Have Toxins that Violate Ecuadorian Law.**

Inspection Site	Samples from Texaco*	Samples from plaintiffs	Sample totals	Samples that violate Ecuadorian law**	% violating Ecuadorian law
SA-6	45	-	45	24	53%
SA-21	36	-	36	23	64%
SA-10	10	2	12	6	50%
SA-65	18	12	30	16	53%
SA-51	32	7	39	21	54%
SA-57	37	-	37	18	49%
SA-53	34	12	46	20	43%
SA-94	27	7	34	18	53%
SSF-67	30	14	44	33	75%
SSF-48	41	16	57	41	72%
SA-18	37	13	50	35	70%
SA-85	21	9	30	22	73%
SA-14	30	18	48	35	73%
SSF-08	22	12	34	22	65%
SSF-04	8	8	16	14	87%
SSF-07	19	10	29	27	93%
SSF-21	17	11	28	21	75%
SACHA CENTRAL	29	9	38	29	76%
SSF-NORTE	48	-	48	31	65%
LAGO NORTE	35	28	63	50	79%
SSF-SUR	51	18	69	34	49%
SSF-SW	14	13	27	17	63%
<b>TOTAL</b>	<b>647</b>	<b>219</b>	<b>866</b>	<b>557</b>	<b>64%</b>

\*Water and soil.

\*\* Decrees 1215 and 3516, which regulate environmental contamination in Ecuador.

- Conclusions:** (1) Of the 866 samples reported by both parties to the court, 557 (64%) violate Ecuadorian law.  
 (2) Of the inspected sites, 100% gave samples with toxin levels that violate Ecuadorian law.